



ENVIRONMENTAL COMPLAINTS & LOCAL SERVICES  
TOTAL RETENTION FACILITIES  
TOTAL RETENTION FACILITIES with LAND APPLICATION  
WASTEWATER BYPASS FORM

RECEIVED

JUN 01 2018

DEQ Facility ID: 5-30601 Facility Name: RW & SD No. 20 County: PITTSBURGH

Report all Total Retention Facility and  
Total Retention Facilities with Land Application  
wastewater bypasses to  
DEQ/ Environmental Complaints and Local Services  
within 24 hours at:

1-800-522-0206

Mail or Fax written report including copies of ANY test results  
within 5 days to:

Department of Environmental Quality  
Environmental Complaints and Local Services  
P.O. Box 1677  
Oklahoma City, OK 73101-1677  
Fax No. (405) 702-6226

DEQ notified: MAY 26 2018 12:12 ☐ AM ☒ PM

Period of bypass: From MAY 26 2018 4:30 ☒ AM ☐ PM

To MAY 26 2018 8:30 ☒ AM ☐ PM

Type of Bypass: ☐ Pipe ☐ Lagoon/Basin ☒ Manhole ☐ Head Works ☒ Lift Station

Strength of Bypass ☒ Raw ☐ Partially Treated Amount of Bypass: ~5,000 - 10,000 GALLONS

Type of samples taken: ☐ BOD ☐ TSS ☐ Fecal ☐ pH ☐ None ☐ Other: E. Coli

Geographical location of bypass and receiving stream if appropriate: CARLTON LANDING LIFT STATION  
N 35°-12'-16.83" / W 095°-32'-33.49" / LAKE EUFAULA N 035°-12'-14.61" / W 095°-32'-28.18"

Reason for bypass: PUMP FAILED TO LIGHT OFF IN "AUTO" MODE - LIFT STATION VELL OVERFLOWED

Steps taken to prevent recurrence: PUMP IS BEING MONITORED EVERY 2-4 HOURS UNTIL SYSTEM CAN BE CHECKED

Were fish or other wildlife affected as a result of the bypass? ☐ Yes ☒ No How? NONE OBSERVED

Impact to receiving stream and/or surrounding areas: LAKE EUFAULA

Steps taken to clean up or treat bypass: FLOW PATH FURTHER W/ CLEAN WATER. LIME APPLIED TO FLOW PATH.

Reported by: CHARLES A KILBURN

Title: PARTNER MANAGER

Signature: Charles A Kilburn

Date: MAY 29, 2018

DEQ EPS USE ONLY:

Type of Contact: ☐ Phone or ☒ Site Visit Date: 5/30/18 Follow up Site Visit ☐ Date:

Geographical location of bypass and receiving stream if appropriate: Carlton landing lift station to beach

Reason for bypass: Lift station pump failure

Steps taken to prevent recurrence: keep two pumps in well and maintain

Impact to receiving stream and/or surrounding areas: minimal

Steps taken to clean up or treat bypass: Lime, pick up litter test area

Corrective action needed: Under current CO Comply by date:

Reported information confirmed: ☒ Yes ☐ No If no, explain:

Comments:

Signature: Jonah M. Schaefer

DEQ Representative

ID #: 284572

Date: 6/1/18